

Facility Name: Utica Resource Operating, LLC – Palmer Well Pad

Facility Location: 39.60806, -81.6686, Wills Township, Ohio

Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL IMAGE/VIDEO LOG

1. Inspector Name: Victoria Nelson	2. Dates of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC – Palmer Well Pad	4. Street Address, City, State: 39.60806, -81.6686, Wills Township, Ohio
5. Number of Images and Videos: 11	6. Archival Record Location: C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2397.mp4	4/18/2019	Emissions from Tank 2411 header line pressure relief device
2	MOV_2398.mp4	4/18/2019	Emissions from Tank 2412 thief hatch
3	MOV_2399.mp4	4/18/2019	Emissions from top of tank battery with view of adjacent residence
4	MOV_2400.mp4	4/18/2019	Emissions from Tank 2413 thief hatch
5	MOV_2401.mp4	4/18/2019	Emissions from Tank 2414 thief hatch
6	MOV_2402.mp4	4/18/2019	Emissions from Tank 2415 thief hatch
7	MOV_2403.mp4	4/18/2019	Emissions from combustor stack
8	MOV_2404.mp4	4/18/2019	Emissions from Separator 2-H
9	MOV_2405.mp4	4/18/2019	Emissions from Separator 3-H

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180034.JPG	4/18/2019 2:37:27 PM	39.60911, -81.667277	Staining and condensate droplets at Tank 2410 thief hatch
2	P4180035.JPG	4/18/2019 2:37:31 PM	39.60911, -81.667277	Staining and condensate droplets at the side of Tank 2410